


## Tips and Techniques

by Tom Arnold

Published in the March 2006 Issue of the  
Scale Staffel Newsletter, Gerald Sullivan, Editor



Good way to shape wing leading edge is to put  
at edge of bench and "wipe" your sanding  
block downwards. Always use fresh sandpaper  
and let it do the cutting, not your hand pressure.